

Notes: Extensive wind-loading from N 1/4 in zone with cracking observed within Wind Cr on slope above pit location