Green River Knoll
Teton Range
WY
**Elevation:** 9800 ft
**Aspect:** S
**Specifics:** Poor pit location

Brenden Cronin
01/06/2017 - 10:00am
**Co-ord:**
**Slope Angle:** 32°
**Wind Loading:** previous

**Stability:** Good
**Air Temperature:** -12°F
**Sky Cover:** CLR
**Precipitation:** NO
**Wind:** W Light Breeze

**HS:** 160
**PS:** 20

**Layer Notes:**
**143-105cm:** Problematic layer




**Notes:** This may have been a poor pit site due to previous loading and lack of a defined sun crust on a S aspect. The layers at 95cm and 65cm may be old sun crust the have sublim

Pit was not dug to ground.

Total height of snow: 210cm