Chattanooga BTL
San Juan Range
CO
Elevation: 10600 ft
Aspect: NE

Grady James
12/16/2018 - 1:00pm
Co-ord: 37.87148N, -107.72920E
Slope Angle: 30°
Wind Loading: no

Stability:
Air Temperature: 10°C
Sky Cover: FEW
Precipitation: NO
Wind: S Calm

HS:65
PS: 20

Layer Notes:
20-5cm: Problematic layer

Specifics: Collapsing, widespread; Collapsing, localized; Cracking; We skied slope



Form	Crystal Size	Moisture	ρ kg/m³	Stability tests & Layer comments
				ECTP6 @20cm
				ECTP9 @20cm
^	3-4			

Notes: