BD (r of gully)
Richmond Ridge
CO
Elevation: 3400 m
Aspect: NE

Steve Schreiber
01/07/2019 - 12:00pm
Co-ord:
Slope Angle: 29°
Wind Loading: yes

Stability: Poor
Air Temperature: -7°C
Sky Cover: BKN
Precipitation: S1
Wind: NW Strong

HS: 115
PS: 25

Layer Notes:
115-104cm: Problematic layer

Specifics: Collapsing, localized; Cracking; Instability rapidly rising





Notes: Observers: Greg McFadden, Steve Schreiber. CAIC reports High Danger rating at all elevations. Weather was quite blustery in the early morning making observations difficult until midday. Significant wind slab is forming in exposed terrain.