East Aspect,Ball Butte
Broken Top
OR
Elevation: 7515 m
Aspect: 60°
Specifics:

Clifford Agocs
12/14/2018 - 12:15pm
Co-ord: 10T 606411W 4880189N
Slope Angle: 18°
Wind Loading: yes

Stability:
Air Temperature: -2°C
Sky Cover: SCT
Precipitation: NO
Wind: S Strong

HS:140
PF:20

Layer Notes:
140-111cm: Problematic layer



Notes: Weather deteriorated dramatically while in the pit. Sky turned to obscured, and there was significant wind transport/heavy drifting