Ovan Stendalsravin
Åreskutan
Sweden
Elevation: 1200 m
Aspect: W

Karin Trolin
24/01/2019 - 11:00
Co-ord:
Slope Angle: 22°
Wind Loading: no

Stability:
Air Temperature: -12°C
Sky Cover: X
Precipitation: NO
Wind: SE Moderate

HS:70
PF:10

Layer Notes:
55-40cm: FC i botten, orsak t flak..
55-40cm: Problematic layer

Specifics: Pit dug in a Ski Area; Pit is representative of backcountry



Form	Crystal Size	Moisture	ρ kg/m³	Stability tests & Layer comments
		D		
				55-40cm: FC i botten, orsak t flak..
◎◎				
				ECTX släppte ovan skaren

Notes: Grävdes i brottkanten till ett flak som pistmaskin dragit loss för några dagar sedan...