Ophir N
San Juan Range
CO
Elevation: 11500 ft
Aspect: 350°
Specifics:

Jason Bushey
01/26/2019 - 1:15am
Co-ord:
Slope Angle: 30°
Wind Loading:

Stability: Fair
Air Temperature: -7°C
Sky Cover:
Precipitation: NO
Wind:

HS: 155
PS: 20

Layer Notes:
65-50cm: Problematic layer



Notes: Two tests, 1/26 and 1/27, same time of day within 100' of eachother. Pits on 1/26 showed CT tests easily but no ECT reaction. On 1/27 was able to get week layer near surface to react, and positive reaction on PST showing PWL still present and bridge not fully there. Pits located below ridgeline sheltered trees.