Cement Creak
Silverton
CO
Elevation: 3048 m
Aspect: W

Samantha Podhurst
02/13/2019 - 3:00pm
Co-ord:
Slope Angle: 34°
Wind Loading: yes

Stability:
Air Temperature: -3.8°C
Sky Cover: OVC
Precipitation: S1
Wind: SW Light Breeze

HS: 112

Layer Notes:
18-0cm: Problematic layer

Specifics: Pit is adjacent to avalanche: crown;



Notes: This is a fracture line profile performed on an slide that occurred right off State Highway 110A, on the east side of the road, across from Niagara Gulch.The approximate width was 50', track ran 80', and the length was 100'. The bed surface was a grassy slope, above a creek, with an unsupportive base.