Mammoth Rock
Eastern Sierra Nevada
CA
Elevation: 9000 ft
Aspect: NE
Specifics: Cracking; Instability rapidly rising

Steve Mace
02/15/2019 - 11:30am
Co-ord:
Slope Angle: 34°
Wind Loading: no

Stability:
Air Temperature:
Sky Cover: OVC
Precipitation: S5
Wind: SW Moderate

HS:370
PS: 35

Layer Notes:
315-310cm: Problematic layer



	Form	Crystal Size	Moisture	ρ kg/m³	Stability tests & Layer comments
370					
360					
350					
340					
330					
320					
310	=				ECTP24 @310cm
300					
290					
280					
270					
0					

Notes: