west Meridian
Beartooths
MT
Elevation: 9765 ft
Aspect: 255°
Specifics: Collapsing, localized; Cracking; We skied slope

Beau Fredlund
12/03/2019 - 1:00pm
Co-ord: 45.02527N, -110.00636E
Slope Angle: 29°
Wind Loading:

Stability:
Air Temperature:
Sky Cover: BKN
Precipitation: NO
Wind: W Light Breeze

HS:125

Layer Notes:
70-69cm: Problematic layer



Notes: Looks too good to be true! Which it was.. Found much shallower and weaker snow 100' vertical higher, and turned around- slab over depth hoar, which would crack easily the length of your skis. Lots of rime from the last 48 hours above 9500' also.