Esja19_12_13
Southwest corner
Iceland
Elevation: 450 m
Aspect: S

Audur Kjartansdottir
13/12/2019 - 12:00
Co-ord:
Slope Angle: 25°
Wind Loading: previous

Stability:
Air Temperature: -8.3°C
Sky Cover: FEW
Precipitation: NO
Wind: NE Moderate

HS:50
PF:25

Layer Notes:
21-22cm: Problematic layer

Specifics: Cracking; Recent avalanche activity on similar slopes; Poor pit location



Notes: Lítill snjór. Gryfja tekin þar sem skafrenningur hafði safnast ofná eldir snjó. Tekið við í Rauðhólum í Esju.