Deer Park Silverton
San Juan Range
CO
Elevation: 11650 ft
Aspect: 349°
Specifics: Collapsing, localized

Chris Johnson
12/14/2019 - 12:50pm
Co-ord: 37.76796N, -107.62591W
Slope Angle: 19°
Wind Loading: no

Stability:
Air Temperature: -6°C
Sky Cover: OVC
Precipitation: S1
Wind: W Light Breeze

HS:115
PF:40

Layer Notes:
72-52cm: Problematic layer



Notes: Second layer of concern is top portion of G-28 layer of facets