Iron Mine
Uinta Range
UT
Elevation: 9100 ft
Aspect: 60°
Specifics: Collapsing, widespread; Cracking; Instability rapidly rising

Tyler St Jeor
12/14/2019 - 11:00am
Co-ord:
Slope Angle: 32°
Wind Loading: no

Stability: Poor
Air Temperature: -8°C
Sky Cover: OVC
Precipitation: S2
Wind: W Moderate

HS: 130

Layer Notes:
60-59cm: Problematic layer



Notes: