Diamond Face
Vail/Summit County
CO
Elevation: 12200 ft
Aspect: NE
Specifics: Pit dug in a Ski Area

Devin Toll
01/04/2020 - 10:00am
Co-ord:
Slope Angle: 33°
Wind Loading: previous

Stability:
Air Temperature:
Sky Cover: CLR
Precipitation: NO
Wind: S Moderate

HS:110
PF:20
PS: 10

Layer Notes:
90-45cm: Problematic layer



Notes: