Dirtyface test pit
Central Cascades, East
WA
Elevation: 5305 ft
Aspect:

Joseph Dellaporta
12/26/2020 - 1:00pm
Co-ord: 47.86241N, -120.80292W
Slope Angle:
Wind Loading: yes

Stability:
Air Temperature: -2°C
Sky Cover: BKN
Precipitation: S1
Wind: W Moderate

HS: 170

Layer Notes:
85-80cm: 12/9 crust
85-80cm: Problematic layer

Specifics: Cracking; Recent avalanche activity on similar slopes; We skied slope



Notes: