Bald Mtn Pass
Uinta Range
UT
Elevation: 10658 ft
Aspect: 15°
Specifics: Collapsing, widespread; Cracking

Mark Staples
01/09/2021 - 11:00am
Co-ord: 40.68557N, -110.89923W
Slope Angle: 14°
Wind Loading:

Stability: Poor
Air Temperature:
Sky Cover:
Precipitation:
Wind:

HS: 105

Layer Notes:
50-45cm: Problematic layer



Notes: We found similar stratigraphy, ECT scores, & snow depths on the other side of the pass. Facets at 45-50 cm look a bit dirty and this layer is easy to see in the pit wall.