Goat Crown
Chugach Range
AK
Elevation: 2849 ft
Aspect: 240°

Andrew Schauer
02/23/2022 - 1:30pm
Co-ord: 61.02417N, -149.07306W
Slope Angle: 38°
Wind Loading: previous

Stability: Poor
Air Temperature:
Sky Cover: OVC
Precipitation: S-1
Wind: Light Breeze

HS: 165

Layer Notes:
117-116cm: Valentine's Day
55-53cm: NY crust
53-45cm: Failure layer
53-45cm: Problematic layer

Specifics: Pit is adjacent to avalanche: crown; Recent avalanche activity on similar slopes



Notes: HS-N-R4-D3-O. Avalanche failed on facets below New Year's crust (layer @ 53-45 cm in pit profile).