Jane's Bench
San Juan Range
CO
Elevation: 10900 ft
Aspect: NE

Chris Dickson
02/24/2022 - 2:00pm
Co-ord:
Slope Angle: 28°
Wind Loading:

Stability:
Air Temperature:
Sky Cover: FEW
Precipitation: NO
Wind: Calm

HS: 180
PF: 50
PS: 30

Layer Notes:
128-125cm: Dust layer
122-121cm: Problematic layer

Specifics: Collapsing, widespread; Cracking; Recent avalanche activity on similar slopes



Notes: