Kaboom @ Copper Mtn
Vail/Summit County
CO
**Elevation:** 11870 ft
**Aspect:** 50°

Nolan Van Harte
12/10/2017 - 12:45pm
**Co-ord:** 13S 399240W 4369642N
**Slope Angle:** 35°
**Wind Loading:**

**Stability:**
**Air Temperature:**
**Sky Cover:** CLR
**Precipitation:** NO
**Wind:** Calm

**HS:**110
**PF:**13

**Layer Notes:**
**97-76cm:** Explosive residue observed
**97-76cm:** Problematic layer

**Specifics:** Pit dug in a Ski Area; Recent avalanche activity on similar slopes; Recent avalanche activity on different slopes; Ski tracks on slope




**Notes:** Quick pit, had to return to building before we could finish. Pit location in dish is significantly more loaded than surrounding terrain. Slope has been mitigated with explosives and ski cuts before recent storm.