Kaboom @ Copper Mtn
Vail/Summit County
CO
Elevation: 11870 ft
Aspect: 50°

Nolan Van Harte
12/10/2017 - 12:45pm
Co-ord: 13S 399240W 4369642N
Slope Angle: 35°
Wind Loading:

Stability:
Air Temperature:
Sky Cover: CLR
Precipitation: NO
Wind: Calm

HS:110
PF:13

Layer Notes:
97-76cm: Explosive residue observed
97-76cm: Problematic layer

Specifics: Pit dug in a Ski Area; Recent avalanche activity on similar slopes; Recent avalanche activity on different slopes; Ski tracks on slope



Notes: Quick pit, had to return to building before we could finish. Pit location in dish is significantly more loaded than surrounding terrain. Slope has been mitigated with explosives and ski cuts before recent storm.