North Ridge Right side
Tenmile Range
CO
Elevation:
Aspect:

Ryan Dineen
12/26/2023 - 11:00am
Co-ord:
Slope Angle:
Wind Loading: yes

Stability:
Air Temperature:
Sky Cover: FEW
Precipitation: NO
Wind: N Moderate

HS:130

Layer Notes:
70-65cm: Problematic layer

Specifics: Pit dug in a Ski Area; Pit is adjacent to avalanche: crown;



Notes: dug above the crown of a slide from a 5# charge