Bighorn
Gore Range
CO
Elevation: 11500 ft
Aspect: NW
Specifics: Cracking

Kelli Rohrig
01/11/2024 - 11:00am
Co-ord:
Slope Angle: 20°
Wind Loading:

Stability:
Air Temperature:
Sky Cover:
Precipitation: S-1
Wind:

HS:120
PF:90

Layer Notes:
107-96cm: Problematic layer



Form	Crystal Size	Moisture	ρ kg/m³	Stability tests & Layer comments
				ECTP4 @96cm failed on NSF **CTV, SP @96cm** On NSF

Notes: