Ershovdleinene
Hemsedalsfjellet
Norway
Elevation: 1150 m
Aspect: SE
Specifics: Poor pit location

Laurids Bartling
05/02/2018 - 13:00
Co-ord: 60.90396N, 8.26979E
Slope Angle: 23°
Wind Loading: yes

Stability:
Air Temperature: -5°C
Sky Cover: OVC
Precipitation: NO
Wind: NE Light Breeze

HS:50
PS: 15

Layer Notes:
25-30cm: Problematic layer
40-50cm: Icy crystals, but not bound



Form	Crystal Size	Moisture	ρ kg/m³	Stability tests & Layer comments
		D		
				STM @30cm Q1
				40-50cm: Icy crystals, but not bound
				ECTX Came out at 33 hits
				CTN No result

Notes: