First Aid
Eastern Alaskan Range (
AK
**Elevation:** 5150 ft
**Aspect:** NW

Andrew Doughty
11/16/2024 - 12:00pm
**Co-ord:** 6V 579739 7009243
**Slope Angle:** 25°
**Wind Loading:** no

**Stability:** Fair
**Air Temperature:** 5°F
**Sky Cover:** SCT
**Precipitation:** S1
**Wind:** Calm

**HS:**80
**PF:**30
**PS:**65

**Layer Notes:**
**35-30cm:** Problematic layer

**Specifics:** Collapsing, localized; We skied slope; Snowmobile tracks on slope




| Form | Crystal Size | Moisture | ρ kg/m³ | Stability tests & Layer comments |
|---|---|---|---|---|
| | | | | ←ECTP15 @35cm |

**Notes:**