lake cleveland tour
Albion Mountains
ID
Elevation: 8635 ft
Aspect: NE
Specifics: Collapsing, localized; Cracking

Clayton Shaw
12/26/2024 - 11:00am
Co-ord: 42.31777N, -113.65530W
Slope Angle: 35°
Wind Loading:

Stability:
Air Temperature:
Sky Cover: X
Precipitation: S1
Wind: W Strong

HS:151
PF:60
PS: 10

Layer Notes:
130-108cm: Problematic layer



Notes: on a short, steep, sheltered rollover tucked in a larger valley