Kamilata - Malyovitsa
Rila
Bulgaria
**Elevation:** 2150 m
**Aspect:** W

Kamen Kyutchukov
04/01/2025 - 10:28
**Co-ord:** 42.18262N, 23.37373E
**Slope Angle:** 30°
**Wind Loading:** yes

**Stability:** Fair
**Air Temperature:** -5°C
**Sky Cover:** FEW
**Precipitation:** NO
**Wind:** Moderate

**HS:**140
**PF:**40
**PS:**4

**Layer Notes:**
**140-115cm:** Wind slab
**140-115cm:** Problematic layer
**115-110cm:** Hollow

**Specifics:** Cracking; Recent avalanche activity on different slopes; Instability rapidly rising




**Notes:** Wind direction: Variable. Mainly from SouthWest/East. Wind loading observed.
Snow accumulation from night before: 6cm
Extreme wind loading on Eastern slopes with one avalanche from the night (Zaeshkia ulei) with no crown (hidden from deposition)
Snow loading observed on Nothern slopes as well and on western slopes in negative forms where S/SW winds were able to deposit.