Crystal Range
Lake Tahoe
CA
Elevation: 9000 ft
Aspect: NE
Specifics: Poor pit location

AJ Kaufmann
01/18/2025 - 1:00pm
Co-ord: 38.85253N, -120.15270W
Slope Angle: 20°
Wind Loading:

Stability: Very Good
Air Temperature: 32°F
Sky Cover: CLR
Precipitation: NO
Wind:

HS:60
PF:0
PS: 0

Layer Notes:
42-35cm: Problematic layer



Notes: Stout crust made digging exceptionally difficult. As a result, pit was only 30cm x 30cm and walls were a bit difficult to access. Uncertain if pit went to ground or another impenetrable ice layer.