Komin Main
Vitosha
Bulgaria
Elevation: 1770 m
Aspect: NE
Specifics: Ski tracks on slope

Kamen Kyutchukov
19/01/2025 - 10:15
Co-ord: 42.60183N, 23.28518E
Slope Angle: 35°
Wind Loading: previous

Stability: Good
Air Temperature: 0°C
Sky Cover: CLR
Precipitation: NO
Wind: Calm

HS:75
PF:15
PS:4

Layer Notes:
75-60cm: Becoming moist due to sun/w
75-60cm: Problematic layer



Form	Crystal Size	Moisture	ρ kg/m³	Stability tests & Layer comments
		M		**75-60cm:** Becoming moist due to sun/w
		D		
▫				**ECTX** No result **CTN**

Notes: Previous obvious wind loading
New snow on top of previous layer from melt/freeze. OK cohesion.
CT test: No result
ECT: no result