6th Tree Chute Temps
Vail/Summit County
CO
Elevation: 11820 ft
Aspect: 225°
Specifics: Pit dug in a Ski Area

ryan evanczyk
03/23/2018 - 9:00am
Co-ord: 39.63388N, -105.86260W
Slope Angle: 37°
Wind Loading:

Stability:
Air Temperature: 2.5°C
Sky Cover: OVC
Precipitation: NO
Wind: W Light Breeze

HS:132
PF:50

Layer Notes:



Form	Crystal Size	Moisture	ρ kg/m³	Stability tests & Layer comments

Notes: Pack consisted of trace PP surfce form on a 2cm MFcr that fails on isolation. Some DF present in upper pack other wise mid pack consists of various FCxr layers with multiple decomposing crusts. DH 5-7mm still present at ground.