Middagsfjellet
Middaksfjellet
Norway
**Elevation:** 377 m
**Aspect:** NW
**Specifics:** Collapsing, localized; Cracking; We skied slope

Daniel Tevik
28/03/2018 - 11:15
**Co-ord:** 34W Cb 86143 65920
**Slope Angle:** 28°
**Wind Loading:** previous

**Stability:**
**Air Temperature:** 0°C
**Sky Cover:** OVC
**Precipitation:** S1
**Wind:** SE Calm

**HS:**170
**PF:**47

**Layer Notes:**
**70-97cm:** Sandwiched layer
**70-97cm:** Problematic layer
**97-115cm:** Large facets
**115-170cm:** Sandwiched layer




| Form | Crystal Size | Moisture | ρ kg/m³ | Stability tests & Layer comments |
|---|---|---|---|---|
| + (／) | 4-2 | D | | |
| ／ (●) | | D | | |
| | | | | ←**ECTP22 @70cm** Q2, Facets on crust |
| ◎◎(□) | 2-4 | D | | **70-97cm:** Sandwiched layer |
| □ | 2-5 | D | | **97-115cm:** Large facets |
| ◎◎(♡) | | D | | **115-170cm:** Sandwiched layer |

**Notes:**