Mikey's Mistake
Turoa
New Zealand
**Elevation:** 2165 m
**Aspect:** SE
**Specifics:**

Dan Struder
29/09/2018 - 10:15
**Co-ord:**
**Slope Angle:** 30°
**Wind Loading:** yes

**Stability:** Good
**Air Temperature:**
**Sky Cover:** CLR
**Precipitation:** NO
**Wind:** NW Moderate

**HS:**155
**PF:**10

**Layer Notes:**
**130-0cm:** Problematic layer




| Form | Size | Moisture | ρ kg/m³ | Stability tests & Layer comments |
|---|---|---|---|---|
| | | | 200 | |
| ⁄ (⁂) | 0.3 | D | | ←CT20, Q2 @140cm Failed on PPgp |
| ♡ | 1 | M | | |
| | | | 220 | ←CT11, Q3 @126cm Failed on PPgp |
| • (⁂) | 0.3 | D-M | | |

**Notes:**