Jones ck top
Bridger Range
MT
Elevation: 8400 ft
Aspect: 310°

Alex Marienthal
11/07/2017 - 12:05pm
Co-ord: 45.82389N, -110.93301W
Slope Angle: 33°
Wind Loading: previous

Stability: Fair Unstable
Air Temperature: -10°C
Sky Cover: CLR
Precipitation: NO
Wind: Calm

HS:98

Layer Notes:
33-28cm: Problematic layer

Specifics: Collapsing, localized; Cracking; Recent avalanche activity on different slopes



Notes: Shady, high elevation aspect. Upper half of snowpack is from storm last weekend. Lower half is series of Sep. to October storms. Obvious signs of instability (i.e., avalanches, cracking, collapsing) confined to recently wind load slopes. Propagation in layer of depth hoar on this slope urges caution/avoidance on steep slopes holding snow from last month.